

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ASH MOUNTAIN ADMINISTRATION BUILDING
(Foothills Visitor Center)
Sequoia and Kings Canyon National Park
Ash Mountain
47050 Generals Highway
Three Rivers Vicinity
Tulare County
California

HABS No. CA-2896

INDEX TO BLACK AND WHITE PHOTOGRAPHS

David G. De Vries, photographer, May 2013

- | | |
|------------|--|
| CA-2896-1 | A LANDSCAPE CONTEXT VIEW TO THE EAST-NORTHEAST, SHOWING THE LOW PROFILE VISITORS' PUBLIC ENTRANCE, AND THE MOUNTAINS BEYOND. |
| CA-2896-2 | NORTHEAST CORNER, LOOKING TOWARDS THE LIBRARY AND A STAFF PICNIC TABLE. |
| CA-2896-3 | OBLIQUE VIEW TO THE SOUTHWEST OF THE ENTIRE EAST REAR ELEVATION, SHOWING HOW THE STRUCTURE IS BUILT INTO THE HILL SLOPE, AND SET AMIDST THE NATIVE OAKS. |
| CA-2896-4 | EAST REAR, CENTRAL PART, SHOWING STAIRCASE TO SECOND FLOOR STAFF OFFICES. |
| CA-2896-5 | EAST REAR, SOUTH PART. |
| CA-2896-6 | WEST FRONT, GROUND FLOOR EXTERIOR CORRIDOR TO OFFICES, LOOKING TO NORTH. |
| CA-2896-7 | WEST FRONT, SECOND FLOOR EXTERIOR CORRIDOR, TO NORTH. |
| CA-2896-8 | SOUTHWEST CORNER OF BUILDING, WHERE NEW AIR CONDITIONING UNITS ARE TO BE INSTALLED. NOTE OAKS AND DECORATIVE GRASS PLANTINGS. |
| CA-2896-9 | EXTERIOR VIEW OF THE "L" SHAPED SPACE FORMED BY THE PUBLIC SPACES AT THE LEFT (WEST), THE HALL AT CENTER CONNECTING THE PUBLIC SPACES WITH THE STAFF SPACES, AND THE SECOND FLOOR STAFF OFFICES AT THE RIGHT (EAST). |
| CA-2896-10 | INTERIOR DETAIL, GROUND FLOOR, EAST REAR, SHOWING NO LOAD BEARING CONNECTION BETWEEN A STRUCTURAL SUPPORT COLUMN AND THE CURTAIN WALL. |