HABS No. CT-359-A

## HISTORIC AMERICAN BUILDINGS SURVEY

## INDEX TO PHOTOGRAPHS

MARK TWAIN CARRIAGE HOUSE (Samuel Clemens Carriage House) 35 I Farmington Avenue Hartford Hartford County Connecticut

Jack E. Boucher, Photographer, November 6, 1995

- CT-359-A-1 EXTERIOR, GENERAL VIEW OF NORTHWEST CORNER FROM THE UMBRA OF MAIN HOUSE

  CT-359-A-2 EXTERIOR, VIEW OF NORTH ELEVATION, WITH SCALE

  CT-359-A-3 EXTERIOR, VIEW OF NORTH ELEVATION, WITHOUT SCALE

  CT-359-A-4 EXTERIOR, VIEW OF NORTH AND EAST ELEVATIONS FROM THE NORTH

  CT-359-A-5 EXTERIOR, VIEW OF THE EAST ELEVATION FROM THE NORTHEAST

  CT-359-A-6 EXTERIOR, VIEW OF THE SOUTH (REAR) ELEVATION

  CT-359-A-7 EXTERIOR, VIEW OF THE WEST ELEVATION FROM THE NORTHWEST

  CT-359-A-8 EXTERIOR, DETAIL VIEW OF THE GRIFFIN ON THE SIDE OF THE NORTHWEST DORMER

  CT-359-A-9 EXTERIOR, DETAIL VIEW OF THE ROOF BRACKET ON THE NORTHEAST CORNER FROM THE NORTHWEST
- CT-359-A-11 EXTERIOR, DETAIL VIEW ROOF BRACKET ON NORTHEAST CORNER FROM THE NORTH, WITHOUT SCALE

FROM THE NORTH, WITH SCALE

CT-359-A-12 INTERIOR, FIRST FLOOR, GENERAL VIEW OF THE CONFERENCE ROOM FROM THE NORTHWEST

MARK TWAIN CARRIAGE HOUSE HABS No. CT-359-A INDEX TO PHOTOGRAPHS (Page 2)

CT-359-A-13 INTERIOR, FIRST FLOOR, LIBRARY, VIEW TO NORTHEAST
CT-359-A-14 INTERIOR, FIRST FLOOR, KITCHEN, VIEW TO THE SOUTHEAST
CT-359-A-15 INTERIOR, FIRST FLOOR, KITCHEN, VIEW TO THE SOUTHWEST
CT-359-A-16 INTERIOR, SECOND FLOOR, NORTHWEST OFFICE, VIEW TO THE WEST