

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

4/30
DC,
WAC,
166-

Addendum to
Frederick Douglass House (Cedar Hill,
John Van Hook House)
1411 W Street, SE
Washington
District of Columbia

HABS No. DC-97

Photographs DC-97-1 to DC-97-9 transmitted to Library of Congress ca. 1963,

Ronald Comedy, Photographer September, 1971

DC-97-10 INTERIOR, DURING RESTORATION

DC-97-11 INTERIOR, STAIRWAY, FIRST FLOOR, DURING RESTORATION

HABS
DC,
WASH.
166-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ADDENDUM TO
FREDERICK DOUGLASS HOUSE
(CEDAR HILL)
(JOHN VAN HOOK HOUSE)
1411 W Street, SE
Washington
District of Columbia

HABS No. DC-97

DC-97-1 through DC-97-11 were transmitted to the Library of Congress.

INDEX TO COLOR TRANSPARENCIES

All color xeroxes were made from a duplicate color transparency.

Walter Smalling, Photographer, October 1977

DC-97-12 (CT) NORTH ELEVATION LOOKING SOUTHWEST

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
DC
WASH,
166-

**ADDENDUM TO
FREDERICK DOUGLASS HOUSE**

HABS No. DC-97

(Cedar Hill)
(John Van Hook House)
1411 W Street, SE
Washington
District of Columbia

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Photographs DC-97-1 to DC-97-9 were transmitted to the Library of Congress in 1963.
Photographs DC-97-10 to DC-97-11 were transmitted to the Library of Congress in 1971.
Photograph DC-97-12 (CT) was transmitted previously to the Library of Congress.

DC-97-13 PERSPECTIVE VIEW OF THE NORTH ELEVATION, LOOKING FROM THE
NORTHEAST